

NEW PRODUCT HIGHLIGHT | OCT2019



febi 109623

to fit:
Audi, Seat, Skoda, Volkswagen, Ford,
Various Models



EN

Harness for engine

Function

Unit injector wiring loom harness which is positioned in the cylinder head. This attaches to the engine wiring loom which is connected to the engine control unit, and controls the diesel injector solenoids.

Cause of failure

Engine misfiring or not starting, due to a poor or broken connection of the wiring harness to the injectors, also deterioration of the wiring insulation causing a short or open circuit.

febi recommends when replacing the diesel injectors that the wiring harness is also replaced in order to reduce the risk of any connection problems. It is also recommended that the rocker cover gasket is replaced at the same time, as they often leak once disturbed.

For more technical information please visit: partsfinder.bilsteingroup.com